























































At Pleasant View (very sandy coarse soil), the moisture sensors were very effective at saving water during the cooler, wet spring weather and also during the fall as days became shorter and cooler at night. During mid to late summer, sensors did not provide as much savings just primarily due to the lack of rainfall and heavy wear on some isolated portions of the fields

On sites with medium to heavy textured soils (native sites, not sand based), such as East Boulder and Harlow Platts soil moisture sensors can become a much more relied upon technology throughout the season.

Most soil moisture sensors on the market today will generally require some monitoring and calibration in order to be effective tools and are not automatically perfect.















